



Riverdale, Nettleham
Lincolnshire
Tree safety survey
16th July 2024





Riverdale, Nettleham, Lincoln

Tree no	Size band	Species	Age class	Condition/ notes	Work required	Priority	Risk category - Nettleham PC
1	S3	Betula pendula Birch	mature	tree in moderate condition, some small OHB's to path, minor deadwood	no action		
2	S3	Betula pendula Birch	mature	tree in moderate condition, minor deadwood	no action		
3	S2	Acer pseudoplatanus Sycamore	semi mature	self-set tree in moderate condition	no action		
4	S2	mixed	mature	'hedge' along bank top/ boundary, including Hawthorn, Hazel, Elder, in moderate condition, has been reduced to 1-2m this year	suggest maintain height in future	1 year	
5	S3	Acer platanoides Norway maple	mature	tree in moderate condition, some ivy on stem	sever ivy	6 months	
6	S4	Fraxinus excelsior Ash	mature	tree in rather poor condition; ivy clad stem, thin foliage, low branches to neighbour and beck, including one snapped hanging branch, minor deadwood, poor pruning in past	sever ivy, remove hanging branch, discuss low branches with neighbour; not yet an actionable nuisance but could crown reduce for long term management (neighbour may contribute to cost)	6 months	
7	S3	Acer platanoides Norway maple	mature	tree in moderate condition, ivy on stem, poor pruning in past	sever ivy	6 months	
8	S2	Crataegus monogyna Hawthorn	mature	group of trees along the bank top, approx 6, in rather poor condition; ivy clad stems, growing to beck, some low branches to beck, deadwood	sever ivy, suggest reduce height to approx 3-4m to avoid failures into beck	6 months	
9	S4	Acer pseudoplatanus Sycamore	mature	tree in moderate condition, but rather poor structure, low branches to beck and neighbour, minor deadwood	remove lowest 5 branches on western side at main stem	6 months	
10	S4	Acer pseudoplatanus Sycamore	mature	tree in moderate condition, twinned stemmed from 2m, rather poor structure, low branches to beck and neighbour, minor deadwood	remove some low smaller branches to clear beck	6 months	
11	S3	Betula pendula Birch	mature	group of 7 trees in grass area, in moderate condition, adapted leans growing to light, some poor pruning in past	no action		
12	S3	Acer platanoides Norway maple	mature	tree in moderate condition, minor deadwood, poor pruning in past	no action		
13	S3	Aesculus hippocastanum Horse chestnut	mature	tree appears to be in moderate condition; some old bleeding canker symptoms, minor deadwood, has been cut back from highway	no action		
14	S3	Salix babylonica Weeping willow	mature	specimen tree in moderate condition, poor pruning in past has resulted in poor structure, reactive growth in stem, minor deadwood	monitor any branch failures - may need pollarding in next couple of years	1 year	
15	S4	Prunus species	mature	tree in moderate condition, thin foliage, minor deadwood, some branches recently pruned, lower stem damage and decay at 2m	no action		
16	S3	Prunus species	mature	tree in moderate condition, minor deadwood, some low branches to neighbour	suggest discuss low branches with neighbour; not an actionable nuisance but could crown lift if an issue- neighbour should contribute to cost	1 year	
17	S3	Acer platanoides Norway maple	mature	tree in moderate condition, minor deadwood, high OHB's to neighbour	no action		
18	S3	Prunus species	mature	tree in rather poor condition; suppressed, thin foliage, low target deadwood, mower damage to roots	no action		

size ranges: S1 to 5m, S2 5-10m, S3 10-15m, S4 15-20m and S5 over 20m